

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
MAKIKO MORI, ET AL.) : Examiner: Robert V. Kostak
Appl. No.: 09/512,105) : Group Art Unit: 2614
Filed: February 24, 2000) : Confirmation No.: 5412
For: IMAGE DISPLAY CONTROL)
SYSTEM AND METHOD :
ALLOWING CONNECTION OF)
VARIOUS KINDS OF IMAGE :
DISPLAYS TO ONE SUPPLY)
SOURCE :
U.S. Patent No.: 7,057,667 B2)
Issued: June 6, 2006 : May 25, 2007

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The fee for this Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Daniel S. Glueck/
Daniel S. Glueck
Attorney for Patentees
Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DSG:jab
DC_MAIN 268064

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,057,667 B1

DATED : June 6, 2006

INVENTOR(S) : MAKIKO MORI, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE AT ITEM (56):

Other Publications, Line 2, "Formal" should read --Format--.

ON THE TITLE PAGE AT ITEM (56), page 2:

Other Publications, Line 9, "1 to 49" should read --i to 49--.

IN THE DRAWINGS, SHEET 3 OF 49 (Fig. 3):

"SYNC
REGEN-
RATION" should read
--SYNC
REGEN-
ERATION--.

COLUMN 8:

Line 64, "signal" should read --signals--.

Line 66, "signal" should read --signals--.

COLUMN 12:

Line 55, "on," should read --on, it--.

COLUMN 13:

Line 37, "step S1," should read --step S11,--.

Line 39, "step S1," should read --step S11,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,057,667 B1

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,057,667 B1

DATED : June 6, 2006

INVENTOR(S) : MAKIKO MORI, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 33:

Line 3, "bed room." should read --bedroom.--.

COLUMN 38:

Line 50, "said the" should read --the--.

Line 62, "source; and" should read --source;--.

COLUMN 39:

Line 5, "source," should read --source; and--.

COLUMN 40:

Line 16, "source," should read --source; and--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,057,667 B1

No. of add'l. copies
@ 30¢ per page

